

CYPRUS TOURISM ORGANISATION

HOTEL ESTABLISHMENTS WITH ACCESS FACILITIES FOR PEOPLE WITH SPECIAL NEEDS

<i>Name of the establishment:</i>	APHRODITE HILLS INTERCONTINENTAL RESORT
<i>Category:</i>	Hotel
<i>Class:</i>	5*
<i>Website:</i>	www.aphroditehills.com
<i>Address:</i>	Kouklia - Pafos

Facilities

1	Parking facilities for disabled	
	1.1 Number of available parking spaces for disabled?	2
	1.2 Proximity of parking places to entrance?	YES
	1.3 Is there adequate signage of parking places (vertical signpost/ floor marking)?	NO
	1.4 Is there access to entrance via an unobstructed accessible route?	YES
	1.5 Is the car park area surface paved (no gravel)?	YES
2	Entrance	
	2.1 Does the entrance door permit easy access (width/opening mechanism)?	YES
	2.2 Number of steps between flat ground and entrance?	N/A
	2.3 Is there a supporting hand rail at the staircase entrance?	N/A
	2.4 Is there a ramp at the entrance?	N/A
	2.4.1 Length of ramp?	N/A
	2.4.2 Slope of ramp (grade angle)?	N/A
	2.4.3 Is there a supporting hand rail at the ramp?	N/A
	2.4.4 Is the ramp floor surface non-slippery?	YES
3	Hotel est. outdoor common areas (beach, gardens, swimming-pool, events area)	
	3.1 Is the route connecting most common outdoor areas accessible?	YES
	3.2 Can a wheelchair maneuver freely in most of the outdoor areas?	YES
	3.3 Is there a swimming-pool?	YES
	3.4 Is there a mechanism for hoisting disabled persons in/out of the swimming-pool?	NO
	3.5 Is there a restroom facility (shower(s) and changing room(s)) by the outdoor swimming-pool for use by persons with disabilities?	YES
	3.6 Is there adequate access to the beach for disabled people?	N/A
	3.7 Is there provision for hotel wheelchairs for use on the beach?	N/A
4	Hotel est. indoor common areas	
	4.1 Are there indoor elevated areas?	YES
	4.1.1 Number of steps?	2
	4.1.2 Availability of access providing ramp connecting ground and elevated areas?	YES
	4.1.3 Length of ramp?	6.1m
	4.1.4 Is there a supporting hand rail for ramp?	YES
	4.1.5 Slope of the ramp (grade angle)?	5%
	4.2 Is there a reception area counter/desk for use by disabled persons (i.e 80cm height)?	NO
	4.3 Is there provision of appropriate tables in meal room	YES
5	Common area restroom/sanitary facilities	
	5.1 Accessible toilet booths for use by disabled?	YES
	5.2 Dimensions (mXm) of toilet	1.8X1.85
	5.3 Does the entrance and toilet door open outwards or does it slide?	YES
	5.4 Are there supporting hand rails on either side of toilet bowl?	YES
	5.4.1 Is there a horizontal wall mounted grab rail on side wall?	YES
	5.4.2 Is there a drop-down rail at the unobstructed side of toilet?	YES
	5.5 Is there an unobstructed height of 65cm below wash basin for wheelchair access?	YES

6	Lifts/Elevators	
6.1	Dimensions (mXm) of lift?	1.12x1.5
6.2	Width (cm) of lift entrance with door(s) open?	95cm
7	Is the corridor to the rooms/apartments carpeted?	YES
8	Rooms/apartments for people with special access needs Ë Specify actual Door No(s):	
8.1	Number of rooms/ apartments for use by disabled =	6
8.2	Does the entrance to room/ apartment have a minimum unobstructed width of 85cm?	YES
8.3	Is the entrance door easy to open?	YES
8.4	Does the room/ apartment have a minimum unobstructed width of 1.2m for wheelchair approach?	1.1m
8.5	Is the floor of the bedroom/ apartment carpeted?	NO
8.6	Is there sufficient unobstructed wheelchair turning / maneuvering space (Minimum 1.5X1.5 m) in the room?	YES
8.7	Are there audible emergency alarms?	YES
8.8	Are there visible emergency alarms?	NO
8.9	Is there unobstructed non-elevated balcony access for wheelchair user?	YES
8.10	Room/ apartment restroom/sanitary facilities	
8.10.1	Entry door width? (minimum 90cm)	95cm
8.10.2	Does the entry door open outwards or does it slide?	YES
8.10.3	Is there a horizontal door shutting bar mounted to the inside surface of the entry door?	YES
8.10.4	Dimensions (mXm) of restroom	3.6X2.1m
8.10.5	Is there unobstructed space of minimum 80cm width by the side of toilet bowl for easy transfer from wheelchair?	YES
8.10.6	Is there an emergency alarm pull cord?	NO
8.10.7	Distance from toilet bowl to nearest side wall?	30cm
8.10.8	Grab handling rails	
i	Is there a mounted horizontal grab rail on the side wall?	YES
i	Is there a drop-down rail at the unobstructed approach side of the toilet bowl?	YES
ii	Should the distance of the toilet bowl be greater than 60cm from the side wall, is there a second drop-down rail?	NO
8.10.9	Wash basin	
i	Is there an unobstructed height of 65cm below wash basin for wheelchair access?	YES
ii	Is there an easy to reach mixer/water tap?	YES
8.10.6	Shower/ Bathtub	
i	Is the shower floor at the same level as the floor level?	YES
ii	Is there a drop-down seat in the shower?	YES
iii	Are there any shower grab rails?	YES
v	Is there a bathtub?	NO
vi	Does the hotel provide special designated adjustable seats for use in the bathtub?	N/A
vii	Are there any grab-rails in the bathtub?	N/A

Remarks:

There is a special bus for disabled

All the levels in the unit provide toilet facilities for disabled

The slope (grade angle) of the swimming-pool is less than 5%